



Civil Aviation Authority

# EMERGENCY MANDATORY PERMIT DIRECTIVE



Number: 2014-001-E

Issue date: 17 January 2014

In accordance with 22(1) of Air Navigation Order 2009 as amended the following action required by this Mandatory Permit Directive (MPD) is mandatory for applicable aircraft registered in the United Kingdom operating on a UK CAA Permit to Fly.

<b>Type Approval Holder's Name:</b> BMAA	<b>Type/Model Designation(s):</b> All SkyRanger, SkyRanger Swift and SkyRanger Nynja
---	---

<b>Title:</b>	<b>Inspection for Material Type – Control Cable Shackles and Elevator Joiner</b>
---------------	--

<b>Manufacturer:</b>	Flylight Airsports Ltd
----------------------	------------------------

<b>Applicability:</b>	All SkyRanger, SkyRanger Swift and SkyRanger Nynja
-----------------------	--

<b>Reason:</b>	A batch of non-optimum stainless steel alloy entered the production process for a limited time. This can result in a reduction of strength and cracking of the affected parts.
----------------	--

<b>Effective Date:</b>	18 January 2014
------------------------	-----------------

<b>Compliance/Action:</b>	<p>Complete the inspection actions in accordance with the procedures in sections 4.1 and 4.2 of Bulletin BMAA SB 2462 Issue 2 within the next 5 flight hours or by 31 January 2014, whichever comes first.</p> <p>Note: there is no need to repeat these inspections if they were performed for issue 1 of this Service Bulletin.</p> <p>At the next Permit to Fly revalidation inspection (on, or after, the 31 January 2014) the BMAA Inspector must confirm that Service Bulletin BMAA SB 2462 Issue 2 has been complied with. This may be confirmed by checking that compliance with the Service Bulletin has been properly recorded in the airframe logbook (see Section 6 of the Service Bulletin).</p>
---------------------------	---

**ENSURE COMPLIANCE WITH THIS MPD IS RECORDED IN THE AIRCRAFT LOGBOOK**

<b>Reference Publications:</b>	BMAA Service Bulletin 2462 Issue 2 can be obtained from: British Microlight Aircraft Association, The Bullring, Deddington, Banbury, Oxfordshire, OX15 0TT, Tel: 01869 336006 Or directly from their website at: <a href="http://www.bmaa.org/pwpccontrol.php?pwplID=9687">http://www.bmaa.org/pwpccontrol.php?pwplID=9687</a>
--------------------------------	--

<b>Remarks:</b>	1. This MPD was not posted for consultation because of the urgency of the requirement.	
	2. Enquiries regarding this Mandatory Permit Directive should be referred to: Aircraft Certification, Airworthiness, Civil Aviation Authority, Safety Regulation Group, Aviation House, Gatwick Airport South, West Sussex RH6 0YR.	
	Tel: +44 (0)1293 573726	Fax: +44 (0)1293 573976
E-mail: Tony.Love@caa.co.uk		