## HELICOPTER TYPE: MD-900

(1) MMEL Item	(2) Rectification Interval		
	(3) N	umber	Installed
		(4) N	umber Required for Despatch
34 Navigation			(5) Remarks or Exceptions
EADI Display on EFIS	C 1	0	May be inoperative for day VFR operations over land provided:
			(a) EHSI is operative in the composite mode, and
			(b) An operative slip indicator is available.